DEPARTMENT of ENVIRONMENTAL SERVICES Water Division - Watershed Management Bureau

LAKE TROPHIC DATA

MORPHOMETRIC: Lake: WEST HILL RESERVOIR Lake Area (ha): 4.05 Town: TROY Cheshire Maximum depth (m): Mean depth (m): River Basin: Connecticut Volume (m³): Relative depth: Latitude: Longitude: Shore configuration: Elevation (ft): Shore configuration: Areal water load (m/yr): Shore length (m): Flushing rate (yr⁻): Watershed area (ha): P retention coeff.: % watershed ponded: ---Lake type: BIOLOGICAL: May 2000 DOM. PHYTOPLANKTON (% TOTAL) #1 #2 #3 PHYTOPLANKTON ABUNDANCE (units/mL) CHLOROPHYLL-A $(\mu g/L)$ DOM. ZOOPLANKTON (% TOTAL) #1 #2 #3 ROTIFERS/LITER MICROCRUSTACEA/LITER ZOOPLANKTON ABUNDANCE (#/L) VASCULAR PLANT ABUNDANCE SECCHI DISK TRANSPARENCY (m) BOTTOM DISSOLVED OXYGEN (mg/L) BACTERIA (E. coli, #/100 ml) #1 #2 #3 SUMMER THERMAL STRATIFICATION: Depth of thermocline (m): Hypolimnion volume (m^3) : Anoxic volume (m³)

HEMICAL: Lake: Town:					WEST HILL RESERVOIR TROY				
					May 2000				
DEPTH (m)									
pH (units)									
A.N.C. (Alkalinity)									
NITRATE NITROGEN									
TOTAL KJELDAHL NITROGEN									
TOTAL PHOSPHORUS									
CONDUCTIVITY (µmhos/cm)									
APPARENT COLOR (cpu)									
MAGNESIUM									
CALCIUM									
SODIUM									
POTASSIUM									
CHLORIDE									
SULFATE									
TN : TP									
CALCITE SATURATION INDEX									
All results in mg/L unless indicated otherwise									
TROPHIC CLASSIFICATION: 2000									
		D.0).	S.D.	PLANT	CI	łL	TOTAL	CLASS
				<u></u>				<u> </u>	
COMMENTS:			·						

- 1. The dam creating West Hill Reservoir is currently considered unsafe and the pond was drained at the time of the visit in 2000. It is no longer considered to be a pond and will not until such time as the dam is re-built.
- 2. A road exists to the dam. No boat ramp exists but a small boat or canoe can be put in at the dam.